

Figure 1: Overview of Top of Laser Mast Well. Flashlight and mirror to try and take photo of worn front bottom wall of mast well.



Figure 2: Mirror shows (somewhat) the rubbed off gelcoat on the front, bottom wall of the mast well. For now, just the gelcoat has been work off in this area. I am looking for a way to reseal, recover this worn area to prevent water from seeping/leaking into the now exposed fiberglass.

